


Index No. P 25

CASS COUNTY LAND CORNER RECORD

T. 133 R. 30 M. 5TH Coordinates: X _____ Y _____
E 1/4 24 Corner common to sections 24 AND 19-133-29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1858
Original monument Post

Species	Bearing	Trees
<u>PINE</u>	<u>PINE</u>	
<u>8"</u>	<u>12"</u>	
<u>S 29 E</u>	<u>N 66 1/2 W</u>	
<u>92 LKS</u>		

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1912 By JOHN CURD
Location filed COUNTY SURVEY RECORD BOOK 'A' P 434-443
Monument FIND OLD CORNER: 8" PINE S 29 E 60.72'
SET 3x3x36" OAK STAKE

Evidence of Subsequent Corner Restoration

Year of search 1998 By CCSO
Fd. 2 1/4" ODIP down 1.0'. I.P. is 11.4' East of
4 36 and 28' West of existing 3 strand barbwire fence.

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>J. PINE</u>	<u>OAK</u>	
<u>10"</u>	<u>8"</u>	
<u>N 8-52 E</u>	<u>S 76-47 E</u>	
<u>131.15'</u>	<u>70.33</u>	

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>W. Oak</u>	<u>W. Oak</u>	<u>W. Oak</u>
<u>10"</u>	<u>6"</u>	<u>10"</u>
<u>N 68° E</u>	<u>S 43° E</u>	<u>S 56° W</u>
<u>83.20'</u>	<u>78.67'</u>	<u>93.78'</u>
		<u>W. Oak</u>
		<u>6"</u>
		<u>N 79° W</u>
		<u>86.82'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument CORNER GPS 11/4/02 CCSO
PK, 6' ± E. OF E Co. Rd. # 36

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____