


Index No. A 21

CASS COUNTY LAND CORNER RECORD

T. 133 R. 31 M. 5TH Coordinates: X _____ Y _____

NE 2 Corner common to sections 1, 2 AND 35, 36-134-31

W.C. 231.0 EAST



EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1858
Original monument W.C. Post 3.50 CH. EAST

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>TAM.</u>	<u>PINE</u>	<u>PINE</u>
Diameter <u>6"</u>	<u>12"</u>	<u>8"</u>
Bearing <u>S 46 W</u>	<u>S 17 E</u>	<u>N 74 E</u>
Distance <u>44 LKS.</u>	<u>39 LKS.</u>	<u>78 LKS.</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 1858 By GLO - ORIGINAL
Location filed _____
Monument Post W.C. 5.84 CH. SOUTH

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>PINE</u>	<u>ASPEN</u>	
Diameter <u>9"</u>	<u>7"</u>	
Bearing <u>S 46 3/4 W</u>	<u>S 37 1/2 E</u>	
Distance <u>41 LKS.</u>	<u>39 LKS.</u>	

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed _____
Monument _____

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____