


T. 133 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 17 Corner common to sections 8 AND 17



○ = Corner

EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1863  
 Original monument Post

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Bearing Trees	
Species <u>Aspen</u>	<u>Aspen</u>
Diameter <u>8"</u>	<u>8"</u>
Bearing <u>N 37 1/4 W</u>	<u>S 22 W</u>
Distance <u>15 LKS</u>	<u>9 LKS</u>

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 1915 By N. D. Gorman  
 Location filed COUNTY BOOK "B" P 490-495  
 Monument SET PROPORTIONALLY

Evidence of Subsequent Corner Restoration  
 Year of search 1985 By Dave Lundecker  
Corner Certificate - Doc # 225840  
End 3" iron w/ cap up 24"  
Survey warning sign next to monument  
on E. end of rock pile

Bearing Trees, Reference Objects  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Bearing Trees, Reference Objects		
<u>J. line</u>	<u>Br. oak</u>	<u>Red oak</u>
<u>9"</u>	<u>6"</u>	<u>11"</u>
<u>N 15 E</u>	<u>S 10 W</u>	<u>S 63 W</u>
<u>48.70'</u>	<u>24.65'</u>	<u>22.48'</u>

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Dave Lundecker - 1985  
Doc. # 225840  
Sept 1902, Twp rd order shows no survey