


Index No. L 21

CASS COUNTY LAND CORNER RECORD

T. 133 R. 31 M. 5TH Coordinates: X _____ Y _____
E 1/4 14 Corner common to sections 13 AND 14



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument POST

Species	Bearing	Trees
<u>OAK</u>	<u>OAK</u>	
<u>18"</u>	<u>16"</u>	
<u>N 57 1/2 E</u>	<u>N 77 W</u>	
<u>7 LKS</u>	<u>46 LKS.</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1912 By JOHN CURD
Location filed COUNTY SURVEY RECORD BOOK "A" P. 496-498
Monument TWO STUMPS OF OLD GWT BTS: OAK N 57 30 E
4.62', 16" OAK N 77 W 30.36' WHICH CHECK WITH OLD
STAKE HOLE SET STAKE

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>OAK</u>	<u>15"</u>	<u>575-36W</u>	<u>61.10'</u>
<u>POPLAR STUMP</u>	<u>10"</u>	<u>510-21W</u>	<u>26.57'</u>

Evidence of Subsequent Corner Restoration

Year of search 5/19/86 By Frazer, Glen Williams
Backhoe

dig in center of road @ split of NE & SE corners
dig 10' E-W 14' N-S 2' deep
.75' fill @ top 1.25' - natural - clay
10/28/86 set 2"x18" telespar with alum. cap
down 10" @ E of road

Bearing Trees, Reference Objects

Power Pole	REF. MON.	REF. MON.
<u>N 29 W</u>	<u>W 85 T</u>	<u>E 85 T</u>
<u>46.61</u>	<u>33.00</u>	<u>33.00</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

1-22-90 Cert. Filed by Walter Curd, RLS 11395
Doc. # 31796e showing 1986 information.

June 1912, Twp rd order shows no survey

Re monumentation certificate prepared _____ By _____
Filed at _____ Date _____