


T. 133 R. 31 M. 5TH Coordinates: X _____ Y _____
M.C. # 17 Corner common to sections 16 AND 17



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1863
 Original monument Post

Bearing Trees
 Species N. PINE W. OAK
 Diameter 20" 6"
 Bearing N10 1/2 W S50 1/4 E
 Distance 96 LKS 47 LKS

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1921 By E. B. Horst
 Location filed County Book "D" P. 8
 Monument Set wood post - W.C.M.C. P. 9 SET 2x4s
I.M. AT W.C.M.C.

Evidence of Subsequent Corner Restoration
 Year of search 1985 By Dave Landecker
Corner Certificate - Doc # 285669
Set 2x2x36" sq. iron w/ aluminum cap
Survey warning sign on top of oak

Bearing Trees, Reference Objects
 Species N. PINE W. OAK
 Diameter 12" 7"
 Bearing N20W WEST
 Distance 46.4' 31.0'

Bearing Trees, Reference Objects

<u>w. oak</u>	<u>w. oak</u>	<u>w. oak</u>	<u>w. oak</u>
<u>10"</u>	<u>9"</u>	<u>8"</u>	<u>12"</u>
<u>North</u>	<u>N10E</u>	<u>N28E</u>	<u>S60E</u>
<u>30.40'</u>	<u>41.07'</u>	<u>16.93'</u>	<u>26.79'</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
Certificate - Dave Landecker - 1985
Doc. # 285669