


Index No. M-N 5

CASS COUNTY LAND CORNER RECORD

T. 133 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC # 22 Corner common to sections 17 AND 18



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument POST

Species	Bearing	Trees
<u>LINDEN</u>	<u>PINE</u>	
<u>5'</u>	<u>28"</u>	
<u>S 77 1/4 E</u>	<u>N 73 1/2 W</u>	
<u>62 LKS</u>	<u>70 LKS</u>	

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Bearing Trees, Reference Objects:

Species	Diameter	Bearing	Distance

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects:

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_