


Index No. N 17

CASS COUNTY LAND CORNER RECORD

T. 133 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 22 Corner common to sections 14, 15, 22, 23



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1863  
Original monument Post

Species	Bearing	Trees	
<u>ASPEN</u>	<u>ASPEN</u>	<u>ASPEN</u>	<u>ASPEN</u>
Diameter <u>10"</u>	<u>8"</u>	<u>9"</u>	<u>8"</u>
Bearing <u>N 27 1/2 E</u>	<u>S 30 E</u>	<u>S 41 1/2 W</u>	<u>N 54 W</u>
Distance <u>19 LKS.</u>	<u>24 LKS.</u>	<u>75 LKS.</u>	<u>40 LKS.</u>

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed 1921 By E. B. Hoest  
Location filed COUNTY BOOK D. P. 9  
Monument SET 2x40" I.M.

**Evidence of Subsequent Corner Restoration**

Year of search 1985 By Dave Landecker  
Corner Certificate - Doc # 285672  
Find 2" iron pipe - set 2x2x36" iron with stamped aluminum cap  
Survey marker sign next to monument

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

**Bearing Trees, Reference Objects**

W. oak	W. oak	TRIN OAK	Br. oak	W. oak
<u>20"</u>	<u>12"</u>	<u>20" stump</u>	<u>16"</u>	<u>29"</u>
<u>N 21 E</u>	<u>S 34 W</u>	<u>S 42 W</u>	<u>N 52 W</u>	<u>N 31 W</u>
<u>13.70'</u>	<u>42.51'</u>	<u>13.0'</u>	<u>14.75'</u>	<u>63.14'</u>

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Dave Landecker - 1985  
Doc # 285672

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_