


T. 133 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 24 Corner common to sections 13:24 AND 18:19-133-30



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1858
 Original monument Post

Species	Bearing	Tree	Distance
<u>PINE</u>	<u>PINE</u>	<u>PINE</u>	<u>PINE</u>
<u>10"</u>	<u>12"</u>	<u>7"</u>	<u>7"</u>
<u>S34E</u>	<u>N68W</u>	<u>N20E</u>	<u>S36W</u>
<u>13 LKS</u>	<u>14 LKS</u>	<u>25 LKS</u>	<u>25 LKS</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

○ = Corner

Subsequent Corner Restoration
 Year surveyed 1915 By _____
 Location filed _____
 Monument 6 DITCH SURVEY BK 5 BOX 2 OF
6 DITCH SURVEY BOOKS, PG 23

Evidence of Subsequent Corner Restoration
 Year of search 1985 10/24 By Freeman
Found 3/4" x 12" I.P. down 0.5' - top bent SE
"B.T." tag on P.P. NE
SET 2" x 2" x 18" TELESPAR man

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

N. PINE	SPRUCE	PUR. POLE	TELE. POST
<u>22"</u>	<u>Y</u>	<u>N52E</u>	
<u>N73W</u>	<u>N50W</u>	<u>N53E</u>	<u>S49E</u>
<u>121.13</u>	<u>45.57</u>	<u>50.70</u>	<u>46.92</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
PLAT - CASTLE ADDITION TO BIG WATER
DEAN ANDERSON 1972
3-19-90 Cert. Filed by Walter Curro, RLS 11395
Doc. #319094 showing 1987 information
JULY 2000 - CCSO
End. in place; 2" x 2" telspar monument
down 1.3'. RLS 21367. Located @ C.R. 101
and @ 45th Ave. SW and 14' E & Driveway N.
REF. TIES:

<u>16" N. Pine</u>	<u>N 73° W</u>	<u>121.13' (fnd. tag)</u>
<u>P. Pole</u>	<u>N 6° E</u>	<u>33.16'</u>
<u>Tel. Ped.</u>	<u>S 49° E</u>	<u>47.11' (fnd. tag)</u>
<u>P. Pole</u>	<u>S 41° W</u>	<u>41.71'</u>

- corner GPS 11/4/02 CCSO
Alum cap, down 1.2', on E #101,
2' ± E of 45th Ave.

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____