


Index No. N7

CASS COUNTY LAND CORNER RECORD

T. 133 R. 31 M. 574 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N<sup>4</sup> 20 Corner common to sections 17, 20



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>OAK</u>	<u>OAK</u>
Diameter <u>14"</u>	<u>15"</u>
Bearing <u>N 29 W</u>	<u>S 2 1/2 W</u>
Distance <u>42 LKS</u>	<u>16 LKS</u>

Original Bearing Trees Found			
Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1985 By Dave Landecker  
Corner Certificate - Doc # 285670  
Set a 2" x 2" x 36" square iron with standard County aluminum monument cap 8" above ground.

Bearing Trees, Reference Objects

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Bearing Trees, Reference Objects

Ash	Basswood	Maple	Clump Basswood
<u>6"</u>	<u>10"</u>	<u>6"</u>	<u>13"</u>
<u>N 58 W</u>	<u>N 20 E</u>	<u>S 38 E</u>	<u>S 80 W</u>
<u>41.60'</u>	<u>30.91'</u>	<u>28.80'</u>	<u>14.92'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Dave Landecker - 1985  
Doc # 285670

Re monumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_