


T. 133 R. 31 M. 5th Coordinates: X _____ Y _____
M.C. # 6 Corner common to sections 22 AND 23



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species ASPEN OAK
Diameter 9" 6"
Bearing S79E N49W
Distance 14 LKS. 23 LKS.

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1921 By E. B. HIRST
Location filed COUNTY BOOK 'D' P. 9
Monument SET 2x48" I.M. W.C.M.C.

Evidence of Subsequent Corner Restoration

Year of search 1985 By Dave Landecker
Corner Certificate - Dec # 285675
Find 2" I.P. - replaced with 2" Sq. iron w/
aluminum cap
Survey marker sign next to monument

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

<u>Br. oak</u>	<u>Red oak</u>	<u>J. Pine</u>	<u>Br. oak</u>
<u>4"</u>	<u>13"</u>	<u>6"</u>	<u>4"</u>
<u>S35E</u>	<u>South</u>	<u>N65W</u>	<u>N30W</u>
<u>74.72'</u>	<u>38.28'</u>	<u>52.61'</u>	<u>33.70'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - WHELOCK SHARES
MYRON LANDECKER 1980
Certificate - Dave Landecker - 1985
Dec # 285675