


Index No. C 21

CASS COUNTY LAND CORNER RECORD

T. 133 R. 32 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 2 Corner common to sections 1 4 2



○ = Corner

EXISTING SURVEYS

Original Government Survey  
Year surveyed 1863  
Original monument Post

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species TAm TAm. \_\_\_\_\_  
Diameter 9" 6" \_\_\_\_\_  
Bearing N 15 3/4 W N 65 1/2 E \_\_\_\_\_  
Distance 149 LKS 70 LKS \_\_\_\_\_

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration  
Year of search April 2005 By R. Eldvik #19645  
Cert. of Survey indicates monument found

Bearing Trees, Reference Objects  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects  
\_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument Oct 2000 A. Eldvik #19845  
Cert. of Survey shows mon. found

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_

Apr. 2003 B. Griva #17253  
Cert. of Survey shows mon. found

\_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_