


T. 133 R. 32 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 12 Corner common to sections 1, 12 and 6, 7-133-31



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1858  
 Original monument Post

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

	Bearing	Trees	
Species	<u>PINE</u>	<u>PINE</u>	<u>PINE</u>
Diameter	<u>11"</u>	<u>11"</u>	<u>6"</u>
Bearing	<u>N75 1/4 E</u>	<u>N4 1/2 W</u>	<u>S46 E</u>
Distance	<u>45 LKS</u>	<u>86 LKS</u>	<u>24 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration  
 Year surveyed 1915 By N.D. GORMAN  
 Location filed COUNTY BOOK "B" P. 490-495  
 Monument FOUND CORNER

Evidence of Subsequent Corner Restoration  
 Year of search 1985 By T. FRIGMAN  
END 1/2" ROD AT END OF FENCE WEST  
SET A 2"x2"x36" TELEGRAPH Pylon  
SURVEY MARKER SIGN POS: W 0.50'

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

JACK PINE	BURR OAK	PUR PILE	CFP
<u>6"</u>	<u>7"</u>		
<u>N 25 W</u>	<u>S 72 E</u>	<u>N 79 E</u>	<u>N 55 E</u>
<u>79.70</u>	<u>156.83</u>	<u>79.10</u>	<u>50.81</u>

E-25

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
1-9-89 Cert. Filed by Walter Curo, RLS 11395  
Doc. # 309784  
3-19-90 Cert. Filed by Walter Curo, RLS 11395  
Doc. # 319092

Remonumentation certificate prepared \_\_\_\_\_  
 Filed at \_\_\_\_\_

By \_\_\_\_\_  
 Date \_\_\_\_\_