


Index No. A 3

CASS COUNTY LAND CORNER RECORD

T. 134 R. 29 M. 5TH Coordinates: X _____ Y _____
N^o 146 Corner common to sections 6 AND 31-135-29



EXISTING SURVEYS

Original Government Survey	
Year surveyed	<u>1865</u>
Original monument	<u>Post</u>

Bearing Trees	
Species	<u>N. Pine</u>
Diameter	<u>16"</u>
Bearing	<u>N11W</u>
Distance	<u>220 Yds.</u>

Original Evidence Found	
Year of search	_____ By _____
Monument found	_____

Original Bearing Trees Found	
Species	_____
Diameter	_____
Bearing	_____
Distance	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1-9-67 By Dean M. Anderson
 Location filed Cert. Filed 5-18-67
 Monument Set Cass County cast iron monument
3" below road surface C.S.A.H. #16.

Bearing Trees, Reference Objects		
Species	<u>Birch</u>	<u>White Oak</u> <u>Norway Pine</u>
Diameter	<u>12"</u>	<u>4"</u> <u>8"</u>
Bearing	<u>NW</u>	<u>North</u> <u>NE</u>
Distance	<u>84.55'</u>	<u>78.50'</u> <u>90.35'</u>

Evidence of Subsequent Corner Restoration

Year of search 1999 By Landecker & Assoc.
Cert. of Survey indicates monument
found.

Bearing Trees, Reference Objects		

A-3

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - AGATE LAKE BEACH
RAYMOND L. ANDERSON 1978

CERTIFICATE - DEAN ANDERSON - 1967