


Index No. A 7

CASS COUNTY LAND CORNER RECORD

T. 134 R. 29 M. 5TH Coordinates: X _____ Y _____
N^{1/4} 5 Corner common to sections 5 AND 32-135-29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>N. PINE</u>	<u>W. PINE</u>	
Diameter <u>12"</u>	<u>35"</u>	
Bearing <u>S10E</u>	<u>NRW</u>	
Distance <u>89 LKS.</u>	<u>48 LKS</u>	

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1916 By E.B. HORST
Location filed COUNTY BOOK B P 538-541
Monument FIND OLD GOVT B.T.S. DEAD 35" W. PINE
NRW 48 LKS, ROTTEN 12" W. PINE S 10 E 89 LKS
SET 2x40" BOILER FLUE
1920, E.B. HORST, COUNTY BOOK C P. 380 FIVE I.M.

Evidence of Subsequent Corner Restoration

Year of search 1966 By CO HWY DEPT
CO RD #16
1" I.P.
1916 also on microf. film - roll 105 BK 66 p. 127
p. 194

Species	Bearing	Trees, Reference Objects
<u>W. BIRCH</u>	<u>PAPLAR</u>	
Diameter <u>5"</u>	<u>7"</u>	
Bearing <u>N 9-30 W</u>	<u>S 19-30 E</u>	
Distance <u>42.7'</u>	<u>60.3'</u>	

1916 B.T.S.

Bearing Trees, Reference Objects

A-7

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - FIRST ADDITION TO MANATAUK
DEAN ANDERSON 1957
PLAT - BIRCH BAY ON AGATE
DEAN ANDERSON 1958
PLAT - TINGDALE BROS. GULL LAKE GARDENS
J.P. LARSEN 1928

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____