


T. 134 R. 29 M. 5TH Coordinates: X _____ Y _____
E 1/4 6 Corner common to sections 5 and 6



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865

Original monument POST

Bearing Trees

Species	<u>W. PINE</u>	<u>W. BIRCH</u>
Diameter	<u>36"</u>	<u>6"</u>
Bearing	<u>S47E</u>	<u>N69W</u>
Distance	<u>69 LKS.</u>	<u>18 LKS.</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 1966 By Co Hwy Dept

Location filed Co. Rd # 16

Monument I.M.

Evidence of Subsequent Corner Restoration

Year of search 11-28-66 By Dean M. Anderson

Set a Cass County Cast Iron monument flush with surface

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Ash	Maple	Birch
5"	8"	6"
East	W-NW	SE
19.00'	13.80'	34.25'

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

PLAT - BIRCH BAY GOLF ULLAS
R.F. SCHNEIDER 1970

PLAT - SKI GULL ACRES
WALLACE BUCKLER 1978?

CERTIFICATE - DEAN ANDERSON - 1967

1999-CCSO
Find. impl. 2 1/2" ADIP flush w/ grd. Located
40' N E Co. Rd. 77 along N. tree line

REF. TIES:

7" G. Ash	N 63° W	21.03'
7" R. Oak	N 14° E	14.11'
10" W. Oak	S 22° E	99.59'
I.P. (RLS 9672)	N 1° W	20.19'

Jul 2002 D. Rasmussen
Cert. of SVY shows mon found

Remonumentation certificate prepared _____

Filed at _____

By _____

Date _____