


Index No. E 3

CASS COUNTY LAND CORNER RECORD

T. 134 R. 29 M. 5TH Coordinates: X _____ Y _____
N 1/4 7 Corner common to sections 6 AND 7



○ = Corner

EXISTING SURVEYS

Original Government Survey
Year surveyed 1863
Original monument POST

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species ASPEN ASPEN
Diameter 10" 10"
Bearing N16E S6W
Distance 47 LKS. 24 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1966 By Co Hwy Dept
Location filed Co Rd #16
Monument 1 1/2" I.P.

Evidence of Subsequent Corner Restoration
Year of search 1-11-67 By Dean M. Anderson
Set Cass County cast iron monument 2"
below road surface.

Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects
Norway Pine Norway Pine Norway Pine
14" 10" 12"
SE South SW
98.1' 47.8' 58.2'

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
CERTIFICATE - DEAN ANDERSON - 1967

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____