


Index No. N 11

CASS COUNTY LAND CORNER RECORD

T. 134 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 R 1 Corner common to sections 16 AND 21



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1865  
Original monument POST

Species	Bearing	Trees
<u>N. PINE</u>	<u>81°</u>	<u>PINE</u>
<u>12"</u>	<u>8"</u>	
<u>S 4 1/2 W</u>	<u>N 21 W</u>	
<u>478 LKS.</u>	<u>303 LKS.</u>	

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Diameter	Bearing	Distance

**Subsequent Corner Restoration**

Year surveyed 1906 By JOHN CURD  
Location filed COUNTY BOOK "B" P 361-363  
Monument SET HUB PROPORTIONALLY

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance

**Evidence of Subsequent Corner Restoration**

Year of search 1977 By CAHILL DEPT  
Co Rd # 105  
1/2" I.P. in place

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance

N-11

**Subsequent Corner Restoration**

Year surveyed 1994 By Grinna 17253  
Location filed CCSO  
Monument Certificate of Survey indicates iron monument found.

MAR 2003 CCSO  
Found I.P. with 3" plumbers cap, flush, on & Co Rd. #105.

<u>10" J. Pine</u>	<u>N 42° W</u>	<u>51.94'</u>
<u>12" N. Pine</u>	<u>S 15° E</u>	<u>66.74'</u>
<u>P-pole</u>	<u>S 38° W</u>	<u>33.70'</u>

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Plat - Oakwood Shores - Myron Lendecker - 1983

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_