


Index No. R 4-5

CASS COUNTY LAND CORNER RECORD

T. 134 R. 29 M. 5TH Coordinates: X _____ Y _____
M.C.# 43 Corner common to sections 17 AND 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865

Original monument Post

Bearing Trees

Species	<u>N. Pine</u>	<u>N. Pine</u>		
Diameter	<u>22"</u>	<u>16"</u>		
Bearing	<u>N51W</u>	<u>S59 1/2 W</u>		
Distance	<u>84 LKS</u>	<u>125 LKS</u>		

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1912 By GLO

Location filed Resurvey

Monument ~~Stumps~~ Found 2 N.P.
Stumps - set 12x10x5 granite stone marked
MC on E. side - 2 grooves on S. face
1.00 chain from edge of lake

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>N.P. stump</u>	<u>N.P. stump</u>	<u>J. Pine</u>	<u>J. Pine</u>
Diameter	<u>25"</u>	<u>20"</u>	<u>7"</u>	<u>7"</u>
Bearing	<u>N51W</u>	<u>S51 1/2 W</u>	<u>N43W</u>	<u>S34E</u>
Distance	<u>84 lks.</u>	<u>127 lks</u>	<u>49 lks.</u>	<u>62 lks.</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration R-4-5

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

PLAT - PINE BEACH
PAUL HALE 1915

PLAT - AUDITORS PLAT OF PINE BEACH
DEAN ANDERSON 1953

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____