


Index No. V 7

CASS COUNTY LAND CORNER RECORD

T. 134 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 32 Corner common to sections 29 and 32



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1865  
Original monument post

**Bearing Trees**

Species	<u>N. PINE</u>	<u>BL. OAK</u>	_____
Diameter	<u>20"</u>	<u>4'</u>	_____
Bearing	<u>N 71 W</u>	<u>S 81 E</u>	_____
Distance	<u>66 LKS.</u>	<u>34 LKS.</u>	_____

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed 1970 By CO. HUNT Dept.  
Location filed CO RD # 18  
Monument F.M. in place

**Evidence of Subsequent Corner Restoration**

Year of search 1999 By CCSO  
Fd 1" square pin 2.5' S. of E

**Bearing Trees, Reference Objects**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Bearing Trees, Reference Objects**

<u>R. Oak</u>	<u>R. Oak</u>	<u>R. Oak</u>	<u>R. Oak</u>
<u>6"</u>	<u>10"</u>	<u>9'</u>	<u>10"</u>
<u>N 70° W</u>	<u>N 25° W</u>	<u>N 58° E</u>	<u>S 10° E</u>
<u>72.03*</u>	<u>41.65*</u>	<u>59.92*</u>	<u>151.44*</u>

\*distance to double head nail

V-7

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_