

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found


Year of search _____ By _____
Location filed:
Monument:

Index No. A 7

CASS COUNTY LAND CORNER RECORD

T. 134 R. 30 M. 5th Coordinates: X _____ Y _____

N 1/4 S Corner common to sections 5 AND 32-135-30



EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1858
Original monument Post

Year of search _____ By _____
Monument found _____

	Bearing	Tree	
Species	<u>SPRUCE</u>	<u>SPRUCE</u>	
Diameter	<u>14"</u>	<u>12"</u>	
Bearing	<u>S56W</u>	<u>N15W</u>	
Distance	<u>24 LKS.</u>	<u>20 LKS.</u>	

Original Bearing Trees Found			
Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Year of search _____ By _____

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed _____
Monument _____

Year of search _____ By _____

