


T. 134 R. 30 M. 5TH Coordinates: X _____ Y _____
E1143 Corner common to sections 2, 3



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1868
 Original monument POST

Bearing Trees

| | | | |
|----------|----------------|--|--|
| Species | <u>W. PINE</u> | | |
| Diameter | <u>28"</u> | | |
| Bearing | <u>N60W</u> | | |
| Distance | <u>167 LKS</u> | | |

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

| | | | |
|----------|--|--|--|
| Species | | | |
| Diameter | | | |
| Bearing | | | |
| Distance | | | |

Subsequent Corner Restoration
 Year surveyed 1915 By N. D. GORMAN
 Location filed COUNTY BOOK 'B' P. 484-495
 Monument FIND OLD GOUT B.T STUMP: 20" W. PINE
N50W 123 LKS SET I.M.
also on microfilm-roll 115 BK79 P. 126

Bearing Trees, Reference Objects

| | | | |
|----------|--|--|--|
| Species | | | |
| Diameter | | | |
| Bearing | | | |
| Distance | | | |

Evidence of Subsequent Corner Restoration
 Year of search 1990 By W. CURRO
END 2" PIPE IN PLACE @ E & INT. SEC
OLD TRAILS 1" UP, NEEDS COR MAINT.

Bearing Trees, Reference Objects

| | | | |
|----------|--|--|--|
| Species | | | |
| Diameter | | | |
| Bearing | | | |
| Distance | | | |

Subsequent Corner Restoration
 Year surveyed 1998 By Landecker 17008
 Location filed CCSO
 Monument Certificate of survey indicates
monument found.

Bearing Trees, Reference Objects

| | | | |
|----------|--|--|--|
| Species | | | |
| Diameter | | | |
| Bearing | | | |
| Distance | | | |

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

