


T. 134 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 1 Corner common to sections 1 AND 6-134-29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1858

Original monument Post

Species	Bearing	Trees
<u>N. PINE</u>	<u>N. PINE</u>	
Diameter <u>20"</u>	<u>14"</u>	
Bearing <u>N 71 E</u>	<u>N 2 W</u>	
Distance <u>443 LKS</u>		

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 11-28-66 By Dean M. Anderson

Location filed \_\_\_\_\_

Monument Set a Cass County iron monument 3" below road surface C.S.A.H. #k.

Species	Bearing	Trees, Reference Objects
<u>White Pine</u>	<u>White Pine</u>	<u>White Pine</u>
Diameter <u>3"</u>	<u>6"</u>	<u>4"</u>
Bearing <u>W-NW</u>	<u>E-NE</u>	<u>SE</u>
Distance <u>41.30'</u>	<u>37.85'</u>	<u>51.30'</u>

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	Bearing	Trees, Reference Objects
_____	_____	_____
_____	_____	_____
_____	_____	_____

C-25

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

CERTIFICATE - DEAN ANDERSON - 1967