Index No. M-N 25

CASS COUNTY LAND CORNER RECORD

T. 13N R. 30W M. 5TH Coordinates: X _____ Y _____

MC #12 Corner common to sections 13 AND 18-13N-29W



EXISTING SURVEYS

Original Government Survey

Year surveyed 1858

Original monument post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	Br. Oak	Aspen		
Diameter	8	8		
Bearing	N62E	S82W		
Distance	28 lks	8 lks		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1918 By E. B. HORST

Location filed COUNTY BOOK "C" P99

Monument SET CORNER.

also on MICROFILM - ROLL 105 BK56 P.140.

Evidence of Subsequent Corner Restoration

Year of search 1964, 1968 By R. F. SCHNEIDER

COUNTY BOOK "O" P.47B PIPE - TIES

1967 - Co Hwy Dept - Co Rd #77 2" I.P. in place and 3 witness trees

Bearing Trees, Reference Objects

Species	OAK	OAK		
Diameter	6"	6"		
Bearing	N70W	N89E		
Distance	23.1'	17.1'		

Bearing Trees, Reference Objects

R. OAK	R. OAK	R. OAK	
10"	14"	12"	
S75W	S60E	N60E	
24.90'	13.35'	11.00'	

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____