


T. 134 R. 30 M. 5TH Coordinates: X _____ Y _____
N/4 21 Corner common to sections 16, 21



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1868
 Original monument Post

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species R. OAK BIRCH
 Diameter 10" 10"
 Bearing S10E N60E
 Distance 28 LKS. 30 LKS.

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

O = Corner

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration
 Year of search 1987 By Dave Lundecker
Corner Certificate - Doc # 302261
Set 4" cast iron monument at proportional position
New culvert in 1987 bears S75W 36.5'

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

<u>Red oak</u>	<u>Burr oak</u>	<u>Red oak</u>	<u>Red oak</u>
<u>12"</u>	<u>11"</u>	<u>12"</u>	<u>5"</u>
<u>N24E</u>	<u>S24E</u>	<u>S47W</u>	<u>N20W</u>
<u>49.82'</u>	<u>49.82'</u>	<u>12.86'</u>	<u>35.44'</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
Certificate - Dave Lundecker - 1987
Doc. # 302261