


T. 134 R. 30 M. 5TH Coordinates: X _____ Y _____
E 14 23 Corner common to sections 23, 24



EXISTING SURVEYS

Original Government Survey

Year surveyed 1868
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>BIRCH</u>	<u>PEPLAR</u>	_____	_____
Diameter	<u>10"</u>	<u>18"</u>	_____	_____
Bearing	<u>S 51 1/2 E</u>	<u>S 43 W</u>	_____	_____
Distance	<u>32 LKS.</u>	<u>30 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1996 By Landecker & Assoc
Location filed _____
Monument Set 2" steel tube with Alum cap from Birch Forest data.

Evidence of Subsequent Corner Restoration

Year of search 1/03 By Landecker & Assoc.
Found Alum cap, 7' E. of fence and 1996 witnesses. A C of L was filed.

Bearing Trees, Reference Objects

Species	<u>Oak</u>	<u>Oak</u>	<u>Oak</u>	<u>Oak</u>
Diameter	<u>36"</u>	<u>10"</u>	<u>18"</u>	<u>12"</u>
Bearing	<u>N 35° E</u>	<u>S 60° E</u>	<u>S 50° W</u>	<u>N 40° W</u>
Distance	<u>30.72'</u>	<u>24.31'</u>	<u>20.08'</u>	<u>22.83'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

P. 21

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
NAT - FIRST ADDITION TO BIRCH FOREST
DEAN ANDERSON 1958

April 2005 B. Grivna #17253
Cert. of Survey indicates monument found

Remonumentation certificate prepared Doc. No. 466363
Filed at CCRO

By #17008
Date 5/9/03