


Index No. R 13

CASS COUNTY LAND CORNER RECORD

T. 134 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 28 Corner common to sections 21, 22, 27, 28



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1868
 Original monument POST

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Species	Bearing	Trees	
<u>POPLAR</u>	<u>BIRCH</u>	<u>R. OAK</u>	<u>PINE</u>
<u>18"</u>	<u>10"</u>	<u>10"</u>	<u>5"</u>
<u>S 85E</u>	<u>S 63W</u>	<u>S 18E</u>	<u>N 60W</u>
<u>28CKS</u>	<u>33LKS.</u>	<u>70LKS.</u>	<u>43LKS.</u>

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

○ = Corner

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration
 Year of search 1987 By Dave Lundecker
Corner Certificate - Doc # 302267
Find 1 1/2" i.p. with small pile of stones around

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects			
<u>N. Pine</u>	<u>W. oak</u>	<u>W. oak</u>	<u>chokecherry</u>
<u>20"</u>	<u>4"</u>	<u>7"</u>	<u>6"</u>
<u>N 54E</u>	<u>S 80E</u>	<u>N 76W</u>	<u>N 20W</u>
<u>43.71'</u>	<u>9.75'</u>	<u>32.22'</u>	<u>31.84'</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
Certificate - Dave Lundecker - 1987
Doc. # 302267

Remuneration certificate prepared _____ By _____
 Filed at _____ Date _____