


Index No. R 19

CASS COUNTY LAND CORNER RECORD

T. 134 R. 30 M. 5TH Coordinates: X _____ Y _____
N14R6 Corner common to sections 23,26



○ = Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1868
Original monument POST

Year of search _____ By _____
Monument found _____

	Bearing Trees		
Species	<u>N. PINE</u>	<u>N. PINE</u>	_____
Diameter	<u>12"</u>	<u>8"</u>	_____
Bearing	<u>N52W</u>	<u>S35W</u>	_____
Distance	<u>27LKS</u>	<u>33LKS</u>	_____

Original Bearing Trees Found			
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 1996 By Landecker & Assoc
Location filed _____
Monument Found 1/2" pipe in rock pile

Year of search 1/03 By Landecker & Assoc
Found 1/2" pipe in rock pile, 86' E
S. of driveway. A cofL was filed.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects			
<u>Oak</u>	<u>poplar</u>	<u>Poplar</u>	<u>Oak</u>
<u>36"</u>	<u>6"</u>	<u>10"</u>	<u>36"</u>
<u>North</u>	<u>S 76° E</u>	<u>S 34° E</u>	<u>N 35° W</u>
<u>96.00'</u>	<u>21.55'</u>	<u>33.50'</u>	<u>27.66'</u>

R-19

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed _____
Monument _____

Year of search _____ By _____

Remonumentation certificate prepared Dec. No. 466365
Filed at CCRO

By #17008
Date 5/9/03