


Index No. R 21

CASS COUNTY LAND CORNER RECORD

T. 134 R. 30 M. 5th Coordinates: X _____ Y _____
NE 26 Corner common to sections R3, R4, R5, R6



O = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1868
 Original monument Post

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Species	Bearing	Trees	Distance
<u>W. PINE</u>	<u>R. OAK</u>	<u>W. PINE</u>	<u>W. PINE</u>
<u>20"</u>	<u>15"</u>	<u>20"</u>	<u>7"</u>
<u>S12 1/2 E</u>	<u>N44 E</u>	<u>S78 3/4 W</u>	<u>N13 W</u>
<u>40 LKS.</u>	<u>61 LKS.</u>	<u>70 LKS.</u>	<u>29 LKS.</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed 1967 By Co Hwy Dept
 Location filed Co R07#77
 Monument 2" 1 1/2"

Evidence of Subsequent Corner Restoration
 Year of search 1996 By Landelcker & Assoc
Found 2" pipe, up 1'.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Poplar</u>	<u>15"</u>	<u>N20°W</u>	<u>18.78'</u>
<u>Oak</u>	<u>12"</u>	<u>N50°E</u>	<u>14.65'</u>
<u>Oak</u>	<u>16"</u>	<u>S50°E</u>	<u>12.70'</u>
<u>Birch (Tri.)</u>	<u>8"</u>	<u>S80°W</u>	<u>22.15'</u>

R-21

Subsequent Corner Restoration
 Year surveyed 1/03 By Landelcker & Assoc.
 Location filed _____
 Monument Found 2" Iron pipe and 1996 witnesses. A C of L was filed.

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
PLAT - BIRCH FOREST
DEAN ANDERSON 1951

Remonumentation certificate prepared Doc No. 466366 By #17008
 Filed at CCRO Date 5/9/03