


Index No. V 23

CASS COUNTY LAND CORNER RECORD

T. 134 R. 30 M. 5TH Coordinates: X _____ Y _____
N 1/4 36 Corner common to sections 25 and 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1868
Original monument POST

Bearing Trees

Species	<u>N. PINE</u>	<u>W. PINE</u>	
Diameter	<u>12"</u>	<u>10"</u>	
Bearing	<u>N70W</u>	<u>S39E</u>	
Distance	<u>17 LKS</u>	<u>8 LKS</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 3-24-04 By D. Lancker #17008
Location filed CCRO # A000498139
Monument 1/2" iron pipe w/ plastic cap stamped
ALS #17008 South 25°W 56.95' from
centerline of Co Rd. 77.

Bearing Trees, Reference Objects

Species	<u>R. PINE</u>	<u>R. OAK</u>	<u>W. PINE</u>
Diameter	<u>12"</u>	<u>12"</u>	<u>14"</u>
Bearing	<u>N22°E</u>	<u>S25°W</u>	<u>S80°W</u>
Distance	<u>128.74'</u>	<u>116.19'</u>	<u>47.04'</u>

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Plat - Timber Ridge Sixth Addition
- Gary Stevenson 1982

Re-monumentation certificate prepared _____ By _____
Filed at _____ Date _____