


Index No. A 25

CASS COUNTY LAND CORNER RECORD

T. 134 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 1 Corner common to sections 1 AND 6-134-30 AND 36-135-31  
AND 31-135-30



○ = Corner

EXISTING SURVEYS

Original Government Survey  
Year surveyed 1858  
Original monument Post

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing Trees			
	<u>ASPEN</u>	<u>ASPEN</u>	<u>ASPEN</u>	<u>ASPEN</u>
Diameter	<u>14"</u>	<u>12"</u>	<u>10"</u>	<u>10"</u>
Bearing	<u>N75E</u>	<u>N34W</u>	<u>S92E</u>	<u>S77W</u>
Distance	<u>12 LKS</u>	<u>26 LKS</u>	<u>17 LKS</u>	<u>21 LKS</u>

Original Bearing Trees Found			
Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration  
Year of search 1996 4-18 By John D. Walker  
Found 2" capped iron pipe (up 0.3) under  
East-West fence. Left monument as found.  
Cert. filed by John D. Walker, RLS 16098,  
Doc. # 408852

Bearing Trees, Reference Objects			
Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects			
Species	Diameter	Bearing	Distance
<u>Oak</u>	<u>9"</u>	<u>N10E</u>	<u>15.02'</u>
<u>Oak</u>	<u>12"</u>	<u>S80W</u>	<u>13.77</u>
<u>Oak</u>	<u>14"</u>	<u>S4W</u>	<u>14.57</u>
<u>Oak</u>	<u>15"</u>	<u>S40E</u>	<u>29.13</u>

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_