


T. 134 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 11 Corner common to sections 1, 2, 11, 12



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1869
 Original monument Post

Species	Bearing	Trees	Distance
<u>ASPEN</u>	<u>ASPEN</u>	<u>ASPEN</u>	<u>ASPEN</u>
<u>4"</u>	<u>5"</u>	<u>5"</u>	<u>4"</u>
<u>S34W</u>	<u>N65W</u>	<u>N35E</u>	<u>S7SE</u>
<u>5LKS</u>	<u>6LKS</u>	<u>12LKS</u>	<u>10 LKS</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration
 Year surveyed 1915 By N. D. Gorman
 Location filed COUNTY BOOK "B" P 484-495
 Monument START FROM CORNER - RUN NORTH POSSIBLE I.M.
1915 - E.B. Hest - COUNTY BOOK "C" P. 88 FND I.M. - RUN EAST
1915 - Gorman - also on microfilm - roll 115BK79 P. 138

Evidence of Subsequent Corner Restoration
 Year of search 1985, 11/1 By Freeman
End 2" 1/2" down 0.1' in R.L. roads
Survey marker sign N45E 46.7'
8-5-87 lowered monument 10"

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

TRI-OAK	BURR OAK	BURR OAK
<u>5" - 8"</u>	<u>13"</u>	<u>8"</u>
<u>N 46 W</u>	<u>S 33 W</u>	<u>S 64 E</u>
<u>54.40</u>	<u>93.08</u>	<u>58.76</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
1-22-90 Cert. Filed by Walter Curo, RLS 11395
Doc. # 317967
Jul 2002 J Kramer 23668
Cert. of Svy shows mon found
Jan 1914, Twp rd order shows no survey
June 1902, Twp rd order shows no survey