


Index No. E 9

CASS COUNTY LAND CORNER RECORD

T. 134 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 8 Corner common to sections 4, 5, 8, 9



EXISTING SURVEYS

Original Government Survey

Year surveyed 1869
Original monument Post

Bearing Trees			
Species	Bearing	Distance	
<u>ASPEN</u>	<u>ASPN</u>	<u>ASPN</u>	<u>ASPN</u>
<u>3"</u>	<u>3"</u>	<u>3"</u>	<u>3"</u>
<u>N78E</u>	<u>N61W</u>	<u>S10E</u>	<u>S31/2W</u>
<u>6 LKS.</u>	<u>11 LKS.</u>	<u>18 LKS.</u>	<u>26 LKS.</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1915 By N. D. Gorman
Location filed COUNTY SURVEY BOOK "B" P 484-495
Monument FND CORNER SET BY WHITELY

Evidence of Subsequent Corner Restoration

Year of search 1992 Oct By Thomas Thiessen
Placed a 12" iron pipe monument. 4-26-94
Cert. Filed by Thomas Thiessen, RLS #16097
Doc # 357104

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Aspen</u>	<u>12"</u>	<u>R.R. Tie Gate</u>	<u>Aspen</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search Jan 1904 By _____
Twp rd order shows no survey
Feb. 1914, Twp rd order shows no survey

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____