


T. 134 R. 31 M. 5TH Coordinates: X _____ Y _____
E149 Corner common to sections 9, 10



O = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1869
 Original monument Post

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees

| | | | | |
|----------|--------------|---------------|-------|-------|
| Species | <u>ASPEN</u> | <u>SPRUCE</u> | _____ | _____ |
| Diameter | <u>20"</u> | <u>18"</u> | _____ | _____ |
| Bearing | <u>S76E</u> | <u>N87W</u> | _____ | _____ |
| Distance | <u>28LKS</u> | <u>24LKS</u> | _____ | _____ |

Original Bearing Trees Found

| | | | | |
|----------|-------|-------|-------|-------|
| Species | _____ | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ | _____ |

Subsequent Corner Restoration
 Year surveyed 10/2000 By CCSO
 Location filed file #2000.023
 Monument Found CIM, down 0.3', on E CR #35, 4' E N. of approach.

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects

| | | | |
|----------|---------------|-------------------|------------------|
| Species | <u>W. Oak</u> | <u>W. Oak</u> | <u>P. Pole</u> |
| Diameter | <u>5"</u> | <u>12"</u> | _____ |
| Bearing | <u>N80°W</u> | <u>S81°E</u> | <u>S41°W</u> |
| Distance | <u>60.61'</u> | <u>54.94' 20d</u> | <u>54.30 20d</u> |

*Distance to double head nail

Bearing Trees, Reference Objects

| | | | |
|----------|-------|-------|-------|
| Species | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument - Corner GPS 10/23/02 CCSO
CIM, on E

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____