


T. 134 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 17 Corner common to sections 8, 9, 16, 17



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1869  
 Original monument Post

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

	Bearing	Trees	
Species	<u>BIRCH</u>	<u>ASPEN</u>	<u>ASPEN</u>
Diameter	<u>8"</u>	<u>3"</u>	<u>3"</u>
Bearing	<u>S18W</u>	<u>N68W</u>	<u>N47E</u>
Distance	<u>24 LKS</u>	<u>24 LKS</u>	<u>11 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration  
 Year surveyed 1915 By N.D. GORMAN  
 Location filed COUNTY BOOK 'B' P 490-495  
 Monument SET CORNER PROPORTIONALLY. POSSIBLE I.M.  
10/30/85 Freeman - searched with locator  
no iron in area of intersection

Evidence of Subsequent Corner Restoration  
 Year of search 5/14/86 By Freeman - Glen Williams  
Backhoe  
dug in intersection of N-S & E-W roads  
dug 10' E-W 12' N-S 2 1/2' deep  
3" top-gravel, 9" fill, 1.5' natural-sandy clay  
found nothing

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

	TELE. BOX	PP	CFP	CFP
Bearing	<u>S 49 W</u>	<u>N 52 W</u>	<u>N 43 E</u>	<u>S 47 E</u>
Distance	<u>33.64</u>	<u>30.85</u>	<u>53.35</u>	<u>45.50</u>

Subsequent Corner Restoration  
 Year surveyed 10/23/80 By Terry Freeman  
 Location filed \_\_\_\_\_  
 Monument Set a 2" x 18" telescop monument  
with aluminum cap down 10" at  
intersection of roads N-S and East  
and trail going west (Reference  
ties on other side).

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
11395  
2-5-90 Cert. Filed by Walter Curo, RLS  
Doc. # 318317  
Jan. 1904, Top rd order shows no survey  
Feb. 1914, Top rd order shows no survey