


T. 134 R. 31 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 14 15 Corner common to sections 14, 15



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1869

Original monument Post

Species	Bearing	Trees
<u>OAK</u>	<u>S48E</u>	<u>3 BLKS.</u>
<u>SPRUCE</u>	<u>S33W</u>	<u>RS LKS</u>
Diameter	<u>6"</u>	<u>6"</u>
Bearing	<u>S48E</u>	<u>S33W</u>
Distance	<u>3 BLKS.</u>	<u>RS LKS</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1908 By JOHN Curo

Location filed COUNTY SURVEY RECORD BOOK "A" P 70-71

Monument END OAK BIT & STUMP OF SPRUCE BIT. Set by 8x36" stone

Evidence of Subsequent Corner Restoration

Year of search 1985 11/1 By Freeman

testimony of Paul Crocker - stone was graded out years ago - possibility of base of stone still in place

5/14/86 Freeman - Glen Williams on backhoe End 8" Sq. stone down 0.4'

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>W. OAK</u>	<u>Triple W. oak survey marker</u>	<u>W. OAK</u>
<u>6"</u>	<u>6"-10"</u>	<u>5</u>
<u>N85E</u>	<u>N52W</u>	<u>west</u>
<u>32.10'</u>	<u>52.0'</u>	<u>20'</u>
		<u>58.23</u>

L-17

Subsequent Corner Restoration

Year surveyed 8/6/87 By Terry Freeman

Location filed \_\_\_\_\_

Monument Drilled hole in found stone and set in two 1/2" irons, one 7 1/2" and one 4 1/2" (Reference ties on other side)

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

L-12-90 Cert. Filed by Walter Curo, RLS 11395 Doc # 317848

Sept. 1905, Twp rd order shows no survey