


Index No. N 19

CASS COUNTY LAND CORNER RECORD

T. 134 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 14 R 3 Corner common to sections 14, 23



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1869  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>ASPEN</u>	<u>ASPEN</u>	
Diameter <u>2"</u>	<u>2"</u>	
Bearing <u>N56E</u>	<u>S10E</u>	
Distance <u>12 LKS</u>	<u>23 LKS.</u>	

Original Bearing Trees Found

Species	Bearing	Trees
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed 5/16/86 By Freeman, Glen Williams  
 Location filed \_\_\_\_\_  
 Monument dug in center of road's fence N  
9' N-S, 12' E-W, 2.5' deep  
3" - top, 9" fill, 1.5' sandy gravel - natural  
found nothing SET 18" TELESPAR

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	Bearing	Trees	Reference Objects
<u>JACK PINE</u>	<u>JACK PINE</u>	<u>CFP</u>	<u>SIGN POST</u>
Diameter <u>7"</u>	<u>5"</u>		
Bearing <u>N36W</u>	<u>S23W</u>	<u>N3W</u>	<u>NORTH</u>
Distance <u>105.65</u>	<u>39.33</u>	<u>33.80</u>	<u>33.00</u>

Bearing Trees, Reference Objects

Species	Bearing	Trees	Reference Objects
_____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

N-19

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
3-19-90 Cert. Filed by Walter Curro, RLS 11395  
Doc. # 319099

Remonumentation certificate prepared \_\_\_\_\_

Filed at \_\_\_\_\_ By \_\_\_\_\_

Date \_\_\_\_\_