


Index No. N 23

CASS COUNTY LAND CORNER RECORD

T. 134 R. 31 M. 5TH Coordinates: X _____ Y _____
N 1/4 24 Corner common to sections 13, 24



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1869
 Original monument lost

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species SPRUCE ASPEN
 Diameter 3" 3"
 Bearing N3W S72W
 Distance 6 BLKS 18 BLKS.

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 5/16/86 By Freeman, Glen Williams
 Location filed Backhoe
 Monument dug in center of road & fences N i S

Evidence of Subsequent Corner Restoration
 Year of search 10/26/82 By Randy Morton
 Found 1 1/2" iron pipe 5" above old blazed stump.

9' N-S 12' E-W 3' deep
6" top 1.75' fill, 9" natural sand & gravel
 Bearing Trees, Reference Objects
 Species CEP CEP E POST ORATE SIGN
 Diameter _____
 Bearing NORTH SOUTH N45E NORTH
 Distance 29.25 27.52 40.93 28.00

Bearing Trees, Reference Objects
Jack Pine Pine stump Jack Pine Poplar
14" 12" 7"
N 50 W N 24 E N 41 E S 52 E
48.49' 16.75' 44.43' 1.86'
 (GLO)

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
10-16-92 Cert. Filed by Randy Morton, PLS 21401
Doc. # 312912

Remonumentation certificate prepared _____
 Filed at _____

By _____
 Date _____