


Index No. N 25

CASS COUNTY LAND CORNER RECORD

T. 134 R. 31 M. 5TH Coordinates: X NE 24 Corner common to sections 13, 24, AND 18, 19-134-30 Y _____



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1858
 Original monument POST

Species	Bearing	Trees	
<u>PINE</u>	<u>PINE</u>	<u>PINE</u>	<u>PINE</u>
Diameter <u>10"</u>	<u>10"</u>	<u>10"</u>	<u>7"</u>
Bearing <u>N 70 E</u>	<u>S 77 W</u>	<u>S 55 E</u>	<u>N 38 W</u>
Distance <u>29 LKS.</u>	<u>21 LKS.</u>	<u>12 LKS.</u>	<u>27 LKS.</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1908 By JOHN CURO
 Location filed COUNTY SURVEY RECORD BOOK # 152-53
 Monument SET FROM TESTIMONY OF COR. SET BY OLD CO. SURVEYOR MR. WHEELY.

Evidence of Subsequent Corner Restoration
 Year of search 5/16/86 By Freeman, Glen Williams Beckhie
Found 8" Sq. Stone down 0.1'
1.8' NW of gate post (old post - will be replaced soon)
SURVEY MARKER SIGN SOUTH 4 FT

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

	<u>CFP</u>	<u>P.P.</u>	<u>BURN OAK</u>
			<u>3"</u>
<u>East</u>	<u>N 22 E</u>	<u>N 8 E</u>	
<u>45.5'</u>	<u>60.6'</u>	<u>98.0'</u>	

N-25
 Subsequent Corner Restoration
 Year surveyed 1990 By W. Coro
 Location filed CCSO
 Monument Filed Cert. of Loc. on 1986 information
- corner GPS 8/15/02 CCSO
8" Sq. stone, down 0.2, near Pt of 45th Ave, 2" ODIP at NW corner of stone, 0.6' from center
April 2004 J. Hansen # 14712
Cert. of Sur. shows mon. found
June 2004 R. Anderson # 10798
Cert. of Sur. shows mon. found

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
 Monument found _____

Remonumentation certificate prepared 1/29/90
 Filed at Cass Co. Recorder # 310243

By W. Coro # 11395
 Date _____