


Index No. N 5

CASS COUNTY LAND CORNER RECORD

T. 134 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 19 Corner common to sections 17, 18, 19, 20



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1869
 Original monument Post

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Species	Bearing	Trees	
<u>SPRUCE</u>	<u>ASPN</u>	<u>ASPN</u>	<u>ASPN</u>
Diameter <u>6"</u>	<u>4"</u>	<u>4"</u>	<u>5"</u>
Bearing <u>N65E</u>	<u>N72W</u>	<u>S32E</u>	<u>S13W</u>
Distance <u>34 LKS.</u>	<u>20 LKS</u>	<u>4 LKS</u>	<u>10 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

○ = Corner

Subsequent Corner Restoration
 Year surveyed 1908 By John Curo
 Location filed COUNTY SURVEY RECORD BOOK A P. 60-61
 Monument ENO FLAT STONE - FITS NE 1/4 BITS
SET BK BK 36" STONE
1915, N. D. BORMAN, COUNTY BOOK B P. 490-495 BEGIN AT
CORNER - RUN EAST POSSIBLE T. M.

Evidence of Subsequent Corner Restoration
 Year of search July 1902 By _____
Trwp rd order shows no survey
Feb. 1914, Trwp rd order shows no survey

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument 7/2002 B. Grivna
Cert. of Surv shows mon found.

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____