


Index No. P 25

CASS COUNTY LAND CORNER RECORD

T. 134 R. 31 M. 5TH Coordinates: X _____ Y _____
E/4 24 Corner common to sections 24 AND 19-134-30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1858
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>ASPEN</u>	<u>ASPEN</u>	
Diameter <u>6"</u>	<u>6"</u>	
Bearing <u>N43W</u>	<u>S65E</u>	
Distance <u>12 LKS</u>	<u>41 LKS.</u>	

Original Bearing Trees Found

Species	Bearing	Trees
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed 5/16/86 By Freeman, Glen, William Backhoe
Location filed _____
Monument dug in center of road's old fence west
3" top, 2' fill, 1' natural gravel
Found nothing SET TELESPAN MON.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing	Trees	Reference Objects
<u>BURR OAK</u>	<u>N. PINE</u>	<u>S. PINE</u>	<u>SIGN BURR OAK</u>
Diameter <u>12"</u>	<u>20"</u>		<u>4"</u>
Bearing <u>N32W</u>	<u>S28W</u>	<u>EAST</u>	<u>S87W</u>
Distance <u>64.22</u>	<u>71.70</u>	<u>33.00</u>	<u>37.35</u>

Bearing Trees, Reference Objects

Species	Bearing	Trees	Reference Objects
_____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1-31-90 Cert. Filed by Walter Curo, RLS 11395
Doc. # 318245
6/2002 B. Grinna
Cert. of SUR shows mon. Found
April 2004 J. Hansen # 14712
Cert. of Sur. Shows mon. found

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____