


Index No. T25

CASS COUNTY LAND CORNER RECORD

T. 134 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 R5 Corner common to sections 25 AND 30-134-30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1858

Original monument POST

Bearing Trees

Species	Bearing	Distance
<u>PITCH PINE</u>	<u>PITCH PINE</u>	
<u>10"</u>	<u>8"</u>	
<u>N45W</u>	<u>S70E</u>	
<u>9 LKS</u>	<u>14 LKS.</u>	

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 5/16/86 By Freeman, Glen Williams Beckhoe

Location filed \_\_\_\_\_

Monument dug in center of road & fence east  
dug 8'E-W 12' N-S 2' deep  
3" top, 9" fill, 1' sandy gravel - natural  
SURVEY MARKER SIGN EAST 20'

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u><del>ROUND OAK</del> BURR OAK</u>	<u>BURR OAK</u>	<u>BURR OAK</u>
<u><del>5"</del></u>	<u>5"</u>	<u>6"</u>
<u>N 43 W</u>	<u>N 82 E</u>	<u><del>8"</del> S 32 W</u>
<u>28.25</u>	<u>25.70</u>	<u>43.30</u>

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

1990 CERTIFICATE FILED\*  
DOC. NO. 318882

April 2004 B. Griving # 17253  
(Cert. of Sur. Shows men found)

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_