


Index No. A 19

CASS COUNTY LAND CORNER RECORD

T. 134 R. 32 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 2 Corner common to sections 2 AND 35



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1858  
 Original monument lost

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Bearing Trees  
 Species ASPEN W. OAK  
 Diameter 14" 7"  
 Bearing N 29 E N 10 W  
 Distance 22 LKS 20 LKS

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration  
 Year of search 1985, 1986 By Surveyors office  
9/19/85 - dug at proportional position (also partial fence S.) Dug 11' E-W x 10' N-S x 3' deep - nothing  
8/14/86 set cast iron monument at proportional position by Comstock & Davis, also fence S. in field.  
Certificate - Curu - 1987 - Doc # 297518

Bearing Trees, Reference Objects  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Bearing Trees, Reference Objects  
CFP P.P. Box OAK  
15"  
N 78° W N 55° E S 73° E  
146.70' 68.75' 129.82'

Subsequent Corner Restoration  
 Year surveyed April 2004 By J. Leas # 42619  
 Location filed \_\_\_\_\_  
 Monument cert. of Sur. shows mon. found

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Walt Curu - 1987  
Doc. # 297518

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_