


Index No. C 5

CASS COUNTY LAND CORNER RECORD

T. 134 R. 32 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E114 6 Corner common to sections 5, 6



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1870  
 Original monument lost

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Bearing Trees  
 Species B. Pine B. Pine  
 Diameter 10" 6"  
 Bearing S76W S69E  
 Distance 14 LKS. 17 LKS.

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 12-26-91 By Thomas Thiessen  
 Location filed Cert. Filed Doc. # 343235  
 Monument Set a 1/2" iron pipe monument  
capped RLS No. 16097  
Monument is located 90'+ South of low area.

Evidence of Subsequent Corner Restoration  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects  
 Species Black Oak Burr Oak Burr Oak  
 Diameter 8" 4" 6"  
 Bearing NW NE SE  
 Distance 36.78' 12.62' 32.91'

Bearing Trees, Reference Objects  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
11-24-92 Cert. Filed by Thomas Thiessen,  
RLS 16097, Doc. # 343235.

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_