


Index No. E 23

CASS COUNTY LAND CORNER RECORD

T. 134 R. 32 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 44 12 Corner common to sections 1, 12



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1870  
Original monument Post

**Bearing Trees**

Species	<u>SP. PINE</u>	<u>N. PINE</u>	_____
Diameter	<u>8"</u>	<u>8"</u>	_____
Bearing	<u>N 4 E</u>	<u>S 16 E</u>	_____
Distance	<u>14 LKS.</u>	<u>16 LKS.</u>	_____

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed 1916 By E. B. HERSI  
Location filed microfilm - roll 115 BK 71 P. 135  
Monument no sign of B.T.S. - all burned

**Evidence of Subsequent Corner Restoration**

Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Bearing Trees, Reference Objects**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_