


Index No. G1

CASS COUNTY LAND CORNER RECORD

T. 134 R. 32 M. 5TH Coordinates: X _____ Y _____
W/4 7 Corner common to sections 7 AND 12-134-33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1858

Original monument lost

Bearing Trees

Species	<u>SP. PINE</u>	<u>SP. PINE</u>		
Diameter	<u>7"</u>	<u>4"</u>		
Bearing	<u>S49W</u>	<u>N33W</u>		
Distance	<u>48 LKS</u>	<u>19 LKS.</u>		

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration G1

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Dave Landecker 1985

Set lost - 2x2x36" iron w/ aluminum cap

4" Burr oak S55°E 55.04'

8" Red oak S48°E 101.42'

10" Red oak S50°W 98.70'

6" Burr oak N60°W 76.05'

Doc. # 283482

- Corner GPS 11/1/02 Cass

PK on E Co. Rd. #67

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____