


Index No. J 13

CASS COUNTY LAND CORNER RECORD

T. 134 R. 32 M. 5TH Coordinates: X _____ Y _____
NE 16 Corner common to sections 9, 10, 15, 16



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
 Original monument POST

Original Evidence Found

Year of search _____ By _____
 Monument found _____

| | | |
|--------------------------|-----------------|-----------------|
| | Bearing Trees | |
| Species <u>ASPEN</u> | <u>SP. PINE</u> | <u>SP. PINE</u> |
| Diameter <u>5"</u> | <u>4"</u> | <u>6"</u> |
| Bearing <u>N 25 W</u> | <u>N 7 E</u> | <u>S 41 E</u> |
| Distance <u>192 LKS.</u> | <u>180 LKS.</u> | <u>206 LKS.</u> |

Original Bearing Trees Found

| | | |
|----------------|-------|-------|
| Species _____ | _____ | _____ |
| Diameter _____ | _____ | _____ |
| Bearing _____ | _____ | _____ |
| Distance _____ | _____ | _____ |

O = Corner

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

| | | |
|----------------|-------|-------|
| Species _____ | _____ | _____ |
| Diameter _____ | _____ | _____ |
| Bearing _____ | _____ | _____ |
| Distance _____ | _____ | _____ |

Bearing Trees, Reference Objects

| | | |
|-------|-------|-------|
| _____ | _____ | _____ |
| _____ | _____ | _____ |
| _____ | _____ | _____ |
| _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____