


Index No. R 9

CASS COUNTY LAND CORNER RECORD

T. 134 R. 32 M. 5TH Coordinates: X _____ Y _____
NE 29 Corner common to sections 20, 21, 28, 29



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	BL. PINE	BL. PINE	SP. PINE
Diameter	8"	8"	7"
Bearing	N63W	S37W	N13 1/2 E
Distance	23 LKS.	24 LKS.	26 LKS.

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1990 By WALT CURD
Location filed CERT. OF LOC. DOC # 325735
Monument 1988 Co. HWY DEPT. FND 3/4" BENT IRON PIPE
RESET COR WITH 2"x2"x6" TELESPAR MON. WITH
ALUM CAP IN NEW RD IN 1990

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	J PINE	R. OAK	R. OAK	R. OAK
Diameter	6"	9"	12"	6"
Bearing	N40W	N15E	S32E	S65W
Distance	87.38	73.61	95.02	107.81

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration R 9

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed _____
Monument _____

Year of search _____ By _____
CERT ~~325735~~ WALT CURD 1990
Doc. # 325735

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____