


Index No. N 13

CASS COUNTY LAND CORNER RECORD

T. 135 R. 29 M. 5th Coordinates: X _____ Y _____
NERI Corner common to sections 15, 16, 21, 22



EXISTING SURVEYS

Original Government Survey
Year surveyed 1865
Original monument Post

Original Evidence Found
Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	Distance
<u>OAK</u>	<u>Bl. PINE</u>	<u>N. PINE</u>	<u>N. PINE</u>
<u>10"</u>	<u>10"</u>	<u>20"</u>	<u>24"</u>
<u>N30 1/2 E</u>	<u>N47 1/2 W</u>	<u>S41 W</u>	<u>S57 1/2 E</u>
<u>136 LKS.</u>	<u>57 LKS.</u>	<u>7 LKS.</u>	<u>90 LKS.</u>

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration
Year of search AUG. 2000 By CCSO
Found in place; 1" ODIP, dwn. 0.3'. Located 6' E of E Rd; 24' E of Fremont Rd.

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Species	Diameter	Bearing	Distance
<u>R. Oak</u>	<u>10"</u>	<u>N 6° E</u>	<u>61.09'</u>
<u>Twin Maple</u>	<u>8"</u>	<u>S 75° E</u>	<u>16.56'</u>
<u>Elm</u>	<u>10"</u>	<u>S 10° E</u>	<u>18.92'</u>
<u>PROP. COR.</u>	<u>I.P.</u>	<u>S 65° W</u>	<u>73.80'</u>

(find. scar) * dist. to dbl. hd. nail

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
PLAT - BIRCHWOOD HILLS
L. KNUDSEN 1922
PLAT - LIVINGSTON'S GULLAKE LOTS
W. J. SPAIN 1974
PLAT - WASEYA WOODS
MYRON LANDECKER 1976

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____