


Index No. E 21

CASS COUNTY LAND CORNER RECORD

T. 135 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 11 Corner common to sections 1, 2, 11, 12



EXISTING SURVEYS

Original Government Survey  
Year surveyed 1869  
Original monument Post

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing Trees			
Species	<u>BL. OAK</u>	<u>BL. OAK</u>	<u>BIRCH</u>	<u>OAK</u>
Diameter	<u>14"</u>	<u>12"</u>	<u>8"</u>	<u>8"</u>
Bearing	<u>N77W</u>	<u>N81E</u>	<u>S71E</u>	<u>S38W</u>
Distance	<u>44 LKS.</u>	<u>23 LKS.</u>	<u>37 LKS.</u>	<u>48 LKS.</u>

	Original Bearing Trees Found			
Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration  
Year surveyed 1916 By JOHN LORO  
Location filed COUNTY BOOK B. P. 369-376  
Monument FIND STONE WHICH CHECKS WITH ROOTS & STUMPS OF OLD GWT BITS SET 2x48" IRON also on microf. la - roll 105 BK 56 P. 25, 33

Evidence of Subsequent Corner Restoration  
Year of search 1971 By Co Hwy Dept Co R. # 29  
2" I.M. in place  
Sept. 1916; Twp rd order shows no survey

	Bearing Trees, Reference Objects			
Species	<u>POPLAR</u>	<u>W. PINE STUMP</u>	<u>POPLAR</u>	<u>BIRCH</u>
Diameter	<u>5"</u>	<u>N 55-05W</u>	<u>6"</u>	<u>4"</u>
Bearing	<u>N 33-50E</u>		<u>S 51-10W</u>	<u>S 38-50E</u>
Distance	<u>55.20</u>	<u>74.10'</u>	<u>51.70'</u>	<u>45.10'</u>

	Bearing Trees, Reference Objects		
	<u>Birch</u>	<u>Poplar</u>	<u>OAK</u>
Diameter	<u>10"</u>	<u>14"</u>	<u>12"</u>
Bearing	<u>NE</u>	<u>NW</u>	<u>SW</u>
Distance	<u>96.2'</u>	<u>101.5'</u>	<u>105.4'</u>

E 21

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search 2000 By CCSO  
Fnd. in place; 2" I.M. flush w/ bit as of 6/7/00 (overlay scheduled for summer of 2000) Located E C.R. 29, E 25<sup>th</sup> Ave. SW, and E old rd. grade to the south.  
REF. TIES:  
16" R. Oak N 48° E 89.24'  
10" R. Oak S 42° E 103.73'  
13" W. Oak S 32° W 95.00'  
P. Pole (TAG) N 34° W 70.33'  
\* distances pulled to dbl. hd. nail  
AUG. 2000 - RESET A MAG NAIL from ties POST. CONSTR.  
Oct. 1903 W. H. Hallett Twp rd order shows survey  
Nov. 1920, Twp rd order shows no survey

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_