


T. 135 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 25 Corner common to sections 24, 25 AND 19, 30-135-29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1858

Original monument lost

Species	Bearing	Trees
<u>W. PINE</u>	<u>ASPEN</u>	<u>SPRUCE</u>
Diameter <u>8"</u>	<u>12"</u>	<u>14"</u>
Bearing <u>S72°4W</u>	<u>N11°2E</u>	<u>N72°4W</u>
Distance <u>176 LKS.</u>	<u>260 LKS.</u>	<u>240 LKS.</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CURO

Location filed COUNTY SURVEY RECORD BOOK "B" P. 57-61

Monument END OLD GOVT B.T. DOWN 8" W. PINE S72°4W
176 LKS. SET STAKE

1920 - E.L. TUSLER, COUNTY BOOK "C" P. 376 END BALT
SET I.M.

Species	Bearing	Trees, Reference Objects	Distance
<u>J. PINE</u>	<u>C.F.P.</u>	<u>ASPEN</u>	<u>J. PINE</u>
Diameter <u>14"</u>	<u>S32-03W</u>	<u>5"</u>	<u>18"</u>
Bearing <u>S31-56E</u>	<u>35.35'</u>	<u>N37-35E</u>	<u>32-55E</u>
Distance <u>115.95'</u>	<u>1915 TIES</u>	<u>66.15'</u>	<u>115.5'</u>

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

← 1915 - also on microfilm - roll 115 BK 948, 140

July 1903, W.H. Hallett
Twp rd order shows survey

Bearing	Trees, Reference Objects

R-25

Subsequent Corner Restoration

Year surveyed 1999 By DNR J. Walker

Location filed State of MN & CCSSO

Monument Certificate of Survey indicates
iron pipe found,
Rod

7/2003 - CCSSO #2001.024 found
3/8" pin, 7'± E. of ♀ PI and
witnessed:

<u>P. Pole</u>	<u>S50°W</u>	<u>49.04'*</u>
<u>16" W. Oak</u>	<u>N80°W</u>	<u>73.55'*</u>
<u>6" W. Oak</u>	<u>N18°E</u>	<u>58.20'*</u>

*distance to double head nail

Evidence of Subsequent Corner Restoration Found

Year of search Aug 1912 By _____

Twp rd order shows no survey